

*Figure 5*

Two callouts have been added for the brackets 19 at either end of the figure.

Callouts have been added for the fan blade housing 151, the fan blade 152, and the fan motor 153 shown near the right hand side of the figure.

A callout has been added for the air inlet 17 near the left hand side of the figure.

A callout for the end plate 11 of the left hand side of the figure has been added.

*Figure 6*

The entire image is shown as a mirror image of the figure as filed.

The fan 15 is shown in greater detail.

A callout for end cap 2 is added near the upper right portion of the figure.

A callout for bracket 19 is added near the bottom of the figure.

A callout for air inlet 17 is added near the bottom of the figure.

A callout for housing 1 is added near the upper left portion of the figure.

A callout for the fan blade housing 151 and the fan blade 152 are added near the upper left hand portion of the figure.

A callout for air outlet 18 is added near the top of the figure.

The user interface 23 and an associated callout are added to be consistent with originally filed Figures 1, 2, and 4.

**REMARKS**

Applicants submit the above proposed changes to the drawings shown in red ink in the attached. Applicants also submit herewith, formal substitute drawings (4 sheets for Figures 1-6) that incorporate the proposed changes. Applicants also submit several changes to the specification. All of these corrections are submitted to make the drawings conform to each other and the specification. No new matter has been added.


In view of the foregoing amendments and remarks, this application should now be in condition for allowance. A notice to this effect is respectfully requested. If the Examiner believes, after this amendment, that the application is not in condition for allowance, the Examiner is requested to call the Applicant's attorney at the telephone number listed below.

If this response is not considered timely filed and if a request for an extension of time is otherwise absent, Applicant hereby requests any necessary extension of time. If there is a fee occasioned by this response, including an extension fee, that is not covered by an enclosed check, please charge any deficiency to Deposit Account No. 23/2825

Respectfully submitted,

**Walter G. Birdsell and William Montague, Jr.,**  
**Applicant(s)**

By:



Robert E. Hunt, Reg. 39,231  
Wolf, Greenfield & Sacks, P.C.  
600 Atlantic Avenue  
Boston, Massachusetts 02210-2211  
Tel. No.: (617) 720-3500  
Attorney's for Applicant(s)

Marked-Up Specification

Please replace the paragraph beginning on page 3, line 12, as follows:

Figure 1 is a right front perspective view of a heater in accordance with an aspect of the invention;

Figure 2 is left front perspective view of a heater shown in Figure 1;

Figure 3 is a bottom view of the heater shown in Figure 1;

Figure 4 is an exploded assembly view of the Figure 1 heater;

Figure 5 is a cross-sectional view taken along lines [A-A] 5-5 as shown in Figure 1; and

Figure 6 is a cross-sectional view taken along lines [B-B] 6-6 as shown in Figure 2.